

Hole No. CB-DAC-2

DRILLING LOG		DIVISION		INSTALLATION		SHEET	
		South Atlantic		Jacksonville District		1 OF 1 SHEETS	
1. PROJECT Dade County Beach Restoration				10. SIZE AND TYPE OF BIT Vibrocure 3-1/2"			
2. LOCATION (Coordinates or Station) X-796.207 Y-593.524				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) MLW			
3. DRILLING AGENCY Alpine Geophysical (Contract)				12. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure			
4. HOLE NO. (As shown on drawing title and file number) CB-DAC-2				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER J. Katsolis				14. TOTAL NUMBER CORE BOXES 1		15. ELEVATION GROUND WATER Tidal	
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.				16. DATE HOLE 5-23-74		STARTED COMPLETED 5-23-74	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE -36.7			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING 82 %			
9. TOTAL DEPTH OF HOLE 19.8'				19. GEOLOGIST: T. M. THORNTON			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
-36.7	0.0						
			Sand, calcareous, little quartz, fine to medium grain, some coarse fragments, some small shells, tan, gray (SP)		1	3-1/2" Vibrocure	
-50.7	14.0		Below 14' fine quartz; very slightly silty, brown (SP)				
-54.7	18.0		silty, dark brown (SM)		2		
-56.5	19.8		Top 1' removed for pollution testing				