

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Jacksonville District		SHEET 1 OF 1 SHEETS	
1. PROJECT Dade County Beach Restoration				10. SIZE AND TYPE OF BIT Vibrocure 3-1/2"			
2. LOCATION (Coordinates or Station) X = 799 4110 Y = 543 671				11. DAYUM FOR ELEVATION SHOWN (TBM or BSL) MLW			
3. DRILLING AGENCY Alpine Geophysical (Contract)				12. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure			
4. HOLE NO. (As shown on drawing title and file number) CB-DAC-29				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER J. Katsolis				14. TOTAL NUMBER CORE BOXES 1			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER Tidal			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE STARTED 5-27-74 COMPLETED 5-27-74			
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE -61.0			
9. TOTAL DEPTH OF HOLE 10.6'				18. TOTAL CORE RECOVERY FOR BORING 100 %			
19. XXXXXXXXXXXXXXXXXXXX GEOLOGIST: T. M. THORNTON							
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX-OR-SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
-61.0	0.0						
-67.0	6.0		SAND, calcareous, fine to medium grain with some coarse shell fragments, few small shells, light tan gray silty (SM)		1	3-1/2" Vibrocure	
-71.0	10.0		Below 6' several lenses of coral				
-71.6	10.6		Hit coral at 10'				