




Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	


Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
Jl-28 #S-1 (2')	—●—	-54.7	SW	#230 - 1.01			1.45	1.26	-0.66	3.22	0.97	Project Name:	Jupiter Island 10
Comments: 10 YR 4/1 Munsell @ 10% Moisture												Analysis Date:	04-22-10
Depths and elevations based on measured values												Analyzed By:	ML
												Easting (X, ft):	966410.
												Northing (Y, ft):	970282.
												Horizontal System:	NAD 1983
												Vertical System:	NAVD 88
American Vibracore Services, Inc. 1215 Wallace Drive Delray Beach, FL 33444													

SIEVE ANALYSIS JUPITER ISLAND 10.GPJ FL DEP ROSS.GDT 6/26/10





Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
Jl-28 #S-2 (3.4')	—●—	-56.1	SW	#230 - 1.15		88.50		-0.19	0.45	3.16	1.33	Project Name:	Jupiter Island 10
Comments: 10 YR 5/1 Munsell @ 10% Moisture												Analysis Date:	04-22-10
Depths and elevations based on measured values												Analyzed By:	ML
							American Vibracore Services, Inc.						
							1215 Wallace Drive						
							Delray Beach, FL 33444						
												Easting (X, ft):	966410.
												Northing (Y, ft):	970282.
												Horizontal System:	NAD 1983
												Vertical System:	NAVD 88





Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
JI-28 #S-3 (6.3')	—●—	-59.0	SW	#230 - 1.31		78.50	0.83	0.73	-0.26	2.54	1	Project Name:	Jupiter Island 10
Comments: 10 YR 5/1 Munsell @ 10% Moisture												Analysis Date:	04-24-10
Depths and elevations based on measured values												Analyzed By:	JR
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  <p>AMERICAN VIBRACORE SERVICES</p> </div> <div> <p>American Vibracore Services, Inc. 1215 Wallace Drive Delray Beach, FL 33444</p> </div> </div>												Easting (X, ft):	966410.
												Northing (Y, ft):	970282.
												Horizontal System:	NAD 1983
												Vertical System:	NAVD 88




Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
JI-28 #S-4 (9')	—●—	-61.7	SW	#230 - 1.51			1.22	1.12	-0.56	3.85	0.88	Project Name:	Jupiter Island 10
Comments: 10 YR 4/1 Munsell @ 10% Moisture												Analysis Date:	04-22-10
Depths and elevations based on measured values												Analyzed By:	ML
												Easting (X, ft):	966410.
												Northing (Y, ft):	970282.
												Horizontal System:	NAD 1983
												Vertical System:	NAVD 88
American Vibracore Services, Inc. 1215 Wallace Drive Delray Beach, FL 33444													



Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
JL-28 PCC #S-1 (6.3')	—●—	-59.0	SP	#230 - 0.42			1.56	1.55	0.48	4.34	0.65	Project Name:	Jupiter Island 10
Comments: 10 YR 5/1 Munsell @ 10% moisture. Sample after calcium carbonate.												Analysis Date:	02-23-10
Depths and elevations based on measured values												Analyzed By:	ML
						American Vibracore Services, Inc. 1215 Wallace Drive Delray Beach, FL 33444						Easting (X, ft):	966410.
												Northing (Y, ft):	970282.
												Horizontal System:	NAD 1983
												Vertical System:	NAVD 88