



Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0	2						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-01
BORING ELEV.	-20.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-01
BORING ELEV.	-20.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	2.9 to 3.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-01
BORING ELEV.	-20.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	4.9 to 5.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-01
BORING ELEV.	-20.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	6.9 to 7.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, few sand to gravel-sized shell, gray (SP)	10YR 6/1	5							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-01
BORING ELEV.	-20.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	8.4 to 8.6 Ft.	SAND, poorly-graded, mostly	10YR 5/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-01
BORING ELEV.	-20.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 6	10.9 to 11.1 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine-grained sand-sized quartz, few									
		clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-01
BORING ELEV.	-20.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0	3						
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-02
BORING ELEV.	-21.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-02
BORING ELEV.	-21.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.9 to 4.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-02
BORING ELEV.	-21.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	7.9 to 8.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	5							
		fine-grained sand-sized quartz, trace									
		silt, few medium to coarse-grained									
		sand-sized shell, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-02
BORING ELEV.	-21.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	11.9 to 12.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-02
BORING ELEV.	-21.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	15.4 to 15.6 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-02
BORING ELEV.	-21.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 6	16.4 to 16.6 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-02
BORING ELEV.	-21.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0	2						
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-03
BORING ELEV.	-25.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-03
BORING ELEV.	-25.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	2.9 to 3.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-03
BORING ELEV.	-25.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	5.9 to 6.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-03
BORING ELEV.	-25.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	9.9 to 10.1 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-03
BORING ELEV.	-25.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	11.2 to 11.4 Ft.	SAND, poorly-graded, mostly	10YR 6/1	0							
		fine-grained sand-sized quartz, trace									
		silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-03
BORING ELEV.	-25.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0	3						
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-04
BORING ELEV.	-16.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-04
BORING ELEV.	-16.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.9 to 4.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, few sand to gravel-sized shell, gray (SP)	10YR 6/1	5							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-04
BORING ELEV.	-16.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	7.9 to 8.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 5/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-04
BORING ELEV.	-16.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	11.9 to 12.1 Ft.	SAND, poorly-graded, mostly fine to	10YR 5/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-04
BORING ELEV.	-16.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	15.9 to 16.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, few sand to gravel-sized shell, gray (SP)	10YR 5/1	5							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-04
BORING ELEV.	-16.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 6	19.4 to 19.6 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-04
BORING ELEV.	-16.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0	4						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-05
BORING ELEV.	-21.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-05
BORING ELEV.	-21.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	2.9 to 3.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-05
BORING ELEV.	-21.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	5.9 to 6.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, few sand to gravel-sized shell, gray (SP)	10YR 6/1	10							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-05
BORING ELEV.	-21.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	7.9 to 8.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-05
BORING ELEV.	-21.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	8.4 to 8.6 Ft.	SAND, poorly-graded, mostly fine to	10YR 5/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-05
BORING ELEV.	-21.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0	2						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-06
BORING ELEV.	-26.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-06
BORING ELEV.	-26.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	2.9 to 3.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-06
BORING ELEV.	-26.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	5.9 to 6.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-06
BORING ELEV.	-26.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	6.9 to 7.1 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-06
BORING ELEV.	-26.1 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0	2						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-07
BORING ELEV.	-21.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-07
BORING ELEV.	-21.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.9 to 4.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-07
BORING ELEV.	-21.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	6.9 to 7.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-07
BORING ELEV.	-21.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	8.9 to 9.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-07
BORING ELEV.	-21.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	10.9 to 11.1 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-07
BORING ELEV.	-21.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0	4						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-08
BORING ELEV.	-12.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-08
BORING ELEV.	-12.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.9 to 4.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, few sand to gravel-sized shell, gray (SP)	10YR 6/1	10							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-08
BORING ELEV.	-12.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	7.9 to 8.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-08
BORING ELEV.	-12.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	11.9 to 12.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-08
BORING ELEV.	-12.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	15.9 to 16.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-08
BORING ELEV.	-12.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 6	16.9 to 17.1 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-08
BORING ELEV.	-12.9 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, little medium to coarse-grained sand-sized shell, gray (SP)	10YR 6/1	15	12						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-09
BORING ELEV.	-22.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded with silt, mostly fine to medium-grained sand-sized quartz, few silt, gray (SP-SM)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-09
BORING ELEV.	-22.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.9 to 4.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-09
BORING ELEV.	-22.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	7.9 to 8.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-09
BORING ELEV.	-22.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	11.9 to 12.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-09
BORING ELEV.	-22.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	15.9 to 16.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-09
BORING ELEV.	-22.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 6	19.4 to 19.6 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-09
BORING ELEV.	-22.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0	4						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-10
BORING ELEV.	-19.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-10
BORING ELEV.	-19.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	4.9 to 5.1 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-10
BORING ELEV.	-19.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	9.9 to 10.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-10
BORING ELEV.	-19.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	14.9 to 15.1 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0							
		medium-grained sand-sized quartz,									
		trace silt, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-10
BORING ELEV.	-19.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	17.9 to 18.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-10
BORING ELEV.	-19.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 6	19.4 to 19.6 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-10
BORING ELEV.	-19.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0	2						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-11
BORING ELEV.	-23.4 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-11
BORING ELEV.	-23.4 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	2.9 to 3.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-11
BORING ELEV.	-23.4 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	4.9 to 5.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-11
BORING ELEV.	-23.4 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	7.4 to 7.6 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-11
BORING ELEV.	-23.4 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	11.4 to 11.6 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-11
BORING ELEV.	-23.4 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, few medium to coarse-grained sand-sized shell, gray (SP)	10YR 6/1	5	6						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-12
BORING ELEV.	-15.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-12
BORING ELEV.	-15.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.9 to 4.1 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	5							
		medium-grained sand-sized quartz,									
		trace silt, few medium to									
		coarse-grained sand-sized shell, gray									
		(SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-12
BORING ELEV.	-15.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	6.4 to 6.6 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, few medium to coarse-grained sand-sized shell, gray (SP)	10YR 6/1	5							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-12
BORING ELEV.	-15.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	7.9 to 8.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-12
BORING ELEV.	-15.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0	4						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-13
BORING ELEV.	-20.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-13
BORING ELEV.	-20.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	4.9 to 5.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-13
BORING ELEV.	-20.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	9.9 to 10.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-13
BORING ELEV.	-20.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	14.9 to 15.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-13
BORING ELEV.	-20.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	18.9 to 19.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-13
BORING ELEV.	-20.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 6	19.4 to 19.6 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-13
BORING ELEV.	-20.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0	2						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-14
BORING ELEV.	-26.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-14
BORING ELEV.	-26.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.9 to 4.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-14
BORING ELEV.	-26.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	4.9 to 5.1 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-14
BORING ELEV.	-26.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	6.9 to 7.1 Ft.	SAND, poorly-graded with clay, mostly	10YR 5/1	0							
		fine to medium-grained sand-sized									
		quartz, few clay, gray (SP-SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-14
BORING ELEV.	-26.8 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 5/1	0	3						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-15
BORING ELEV.	-28.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 5/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-15
BORING ELEV.	-28.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	3.4 to 3.6 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 5/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-15
BORING ELEV.	-28.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	4.9 to 5.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 5/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-15
BORING ELEV.	-28.3 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1	0.9 to 1.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0	2						

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borring Area
BORING NO.	VB-SJES25-16
BORING ELEV.	-25.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 1a	1.0 to 1.2 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-16
BORING ELEV.	-25.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 2	4.9 to 5.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-16
BORING ELEV.	-25.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 3	9.9 to 10.1 Ft.	SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace clay, gray (SP)	10YR 6/1	0							

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-16
BORING ELEV.	-25.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02




Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 4	14.9 to 15.1 Ft.	SAND, poorly-graded, mostly fine to	10YR 6/1	0							
		medium-grained sand-sized quartz,									
		trace clay, gray (SP)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-16
BORING ELEV.	-25.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02



Sample No.	Depth	Classification	Munsell	Visual % Shell (est)	%CO_3	G_s	Org %	w_n	LL	PL	PI
● 5	15.9 to 16.1 Ft.	SAND, clayey, mostly fine to	10YR 5/1	0							
		medium-grained sand-sized quartz,									
		few clay, gray (SC)									

GRADATION CURVES

PROJECT	St. Johns County Ebb Shoal Borrow Area
BORING NO.	VB-SJES25-16
BORING ELEV.	-25.6 Ft., NAVD88
DATE	1/27/2026

SAJ FORM 2087
JUN 02