DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30060

WORK ORDER: 6846
REQUISITION: RM-CW-93-0145



Sample No.	Depth/Elev	Visual Classification	Nat w%	LL	PL	PI
--	0.0-5.0'	Grayish tan poorly graded sand (SP), with a trace of shell fragments (gravel and sand sizes). Visual percent shell is approximately 5%.	25.2	--	--	--

Project Nassau County, FL
Beach Erosion Control
Lab No. 73/5435
Boring No. NC92-11
Date 01/07/93

GRADATION CURVES