DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30060

WORK ORDER: 6846
REQUISITION: RM-CW-93-0145



Sample No.	Depth/Elev	Visual Classification	Nat w%	LL	PL	PI
--	0.0-5.0'	Tan poorly graded silty sand (SP-SM), with a trace of shell fragments. Visual percent shell is approximately 5%.	21.9	--	--	--

Project Nassau County, FL
Beach Erosion Control
Lab No. 73/5433
Boring No. NC92-9
Date 01/07/93

GRADATION CURVES

DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30060

WORK ORDER: 6846
REQUISITION: RM-CW-93-0145



Sample No.	Depth/Elev	Visual Classification	Nat w%	LL	PL	PI
–	5.0-10.0'	Gray and tan silty sand (SM) with a trace of shell fragments (gravel and sand sizes). Visual percent shell is approximately 5%.	27.6	–	–	–

Project Nassau County, FL
Beach Erosion Control
Lab No. 73/5434
Boring No. NC92-9
Date 01/07/93

GRADATION CURVES