DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30060

WORK ORDER: 6846
REQUISITION: RM-CW-93-0145



Sample No.	Depth/Elev	Visual Classification	Nat w%	LL	PL	PI
--	5.0-8.0'	Gray poorly graded silty sand (SP-SM), with a trace of shell fragments. Visual percent shell is approximately < 5%.	23.8	--	--	--

Project Nassau County, FL
Beach Erosion Control
Lab No. 73/5443
Boring No. NC92-18
Date 01/07/93

GRADATION CURVES

DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30060

WORK ORDER: 6846
REQUISITION: RM-CW-93-0145



COBBLES	GRAVEL		SAND			SILT OR CLAY
	COARSE	FINE	COARSE	MEDIUM	FINE	

Sample No.	Depth/Elev	Visual Classification	Nat w%	LL	PL	PI
--	8.0-10.0'	Gray silty sand (SM). Visual percent shell is approximately < 1%.	35.6	--	--	--

Project Nassau County, FL
Beach Erosion Control
Lab No. 73/5444
Boring No. NC92-18
Date 01/07/93

GRADATION CURVES