DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30060

WORK ORDER: 6846
REQUISITION: RM-CW-93-0145



Sample No.	Depth/Elev	Visual Classification	Nat w%	LL	PL	PI
–	0.0-5.0'	Tan poorly graded sand (SP), with a trace of shell fragments. Visual percent shell is approximately < 5%.	30.6	–	–	–

Project Nassau County, FL

Beach Erosion Control

Lab No. 73/5448

Boring No. NCF92-2

Date 01/07/93

GRADATION CURVES

DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30060

WORK ORDER: 6846
REQUISITION: RM-CW-93-0145



Sample No.	Depth/Elev	Visual Classification	Nat w%	LL	PL	PI
--	10.0-15.0'	Tan poorly graded silty sand (SP-SM). Visual percent shell is approximately < 1%.	33.9	--	--	--

Project Nassau County, FL
Beach Erosion Control
Lab No. 73/5449
Boring No. NCF92-2
Date 01/07/93

GRADATION CURVES