

GAHAGAN & BRYANT ASSOCIATES

P.O. BOX 18505 TEL. 813-879 5871

TAMPA, FLORIDA 33679

LOG OF BORING

SUBJECT Jupiter Island
 BORING LOCATION _____
 X - 771600 Y - 1030480
 GROUNDWATER DEPTH _____ DATE _____
 DRILL ROD SIZE AW CASING SIZE BW
 BORING BEGUN _____ BORING COMPLETED _____
 TIME AT START 1200 TIME AT FINISH 1415
 TIDE AT START +0.1 TIDE AT FINISH +1.0
 GEOLOGIST _____

BORING NO. 19
 CLIENT Jupiter Island
 DATE 7-5-76 SHEET 1 OF 1
 DRILL RIG Bore Hog
 DRILLER Rowland
 LENGTH OF CASING SET 18'
 GROUND ELEVATION _____ DATUM MLW

ELEVATION	DEPTH IN FEET	SOIL GRAPH	MATERIAL DESCRIPTION	REMARKS	SAMPLE NUMBER	BLOWS/FOOT		DEPTH IN FEET
						ON SAMPLER	ON CASING	
5.8	1		Water					1
	2							2
	3							3
	4							4
	5							5
	6							6
10.5	7		Broken Shell and Medium to Fine Sand		19-1	2	5	7
	8					3	7	8
	9						18	9
	10						19	10
	11						31	11
	12					14	21	12
15.3	13		Fine to Medium Sand with Crushed Shell and Small Shell Fragments	No recovery on Spoon Sample Attempts at 11-13', 16- 18' & 18-20'		12	45	13
	14						69	14
	15						68	15
	16						71	16
	17					32	19	17
	18					11	27	18
19.0	19		Shell Fragments and Sand			15		19
	20					16		20