

# GAHAGAN & BRYANT ASSOCIATES

P.O. BOX 18505 TEL. 813-879 5871

TAMPA, FLORIDA 33679

## LOG OF BORING

SUBJECT Jupiter Island

BORING LOCATION \_\_\_\_\_

X - 769,530 Y - 1,030,930

GROUNDWATER DEPTH \_\_\_\_\_ DATE \_\_\_\_\_

DRILL ROD SIZE AW CASING SIZE BW

BORING BEGUN \_\_\_\_\_ BORING COMPLETED \_\_\_\_\_

TIME AT START 0925 TIME AT FINISH 1050

TIDE AT START +0.3 TIDE AT FINISH -0.2

GEOLOGIST \_\_\_\_\_

BORING NO. 23

CLIENT \_\_\_\_\_

Jupiter Island

DATE 7--7-76 SHEET 1 OF 1

DRILL RIG Bore Hog

DRILLER Rowland

LENGTH OF CASING SET 18'

GROUND ELEVATION \_\_\_\_\_ DATUM MLW

ELEVATION	DEPTH IN FEET	SOIL GRAPH	MATERIAL DESCRIPTION	REMARKS	SAMPLE NUMBER	BLOWS/FOOT		DEPTH IN FEET
						ON SAMPLER	ON CASING	
	1							1
	2							2
	3							3
	4							4
4.7	5		Water					5
5.7	6		Medium Sand and Shell Fgmts.		23 1A	3	8	6
	7		Fine Sand and Shell Fragments		23 1B	13	27	7
	8						25	8
	9						29	9
	10						36	10
10.8	11				23- 2	6	16	11
	12		Shell Fragments and Soft Clay			1	13	12
12.9	13						12	13
	14		Soft Shelly Clay				12	14
	15						16	15
	16					6	36	16
17.0	17					2	37	17
	18		Medium Stiff Clay				36	18
	19				23-3	3		19
20.2	20					1		20