



Sample No.	Elev / Depth	Classification	Nat w %	LL	PL	PI
C7-5.5	-38.5 / 5.5	SAND, poorly graded, med to fine quartz, VIS: 10% shell (SP)				
<div> <div>Project</div> <div>Ft. Pierce, FL, Shore Protection Project</div> </div> <div> <div>Area</div> <div>South Atlantic</div> </div> <div> <div>Boring No.</div> <div>CB-STL-C7</div> </div> <div> <div>Date</div> <div>01/09/1995</div> </div>						
<div> <div>GRADATION CURVES</div> </div>						





Sample No.	Elev / Depth	Classification	Nat w %	LL	PL	PI	Project
C7-8.5	-39.5 / 8.5	VIS Class: Silty SAND, prly grd, (SP-SM) fine quartz, 10% shell					Ft. Pierce, FL, Shore Protection Project
							Jacksonville District
							South Atlantic
							CB-STL-C7
							Boring No.
							Date
							01/09/1995

GRADATION CURVES