



Sample No.	C10-0.9	Elev / Depth	-29.9 / 0.9	Classification	SAND, poorly graded, med quartz & shell, shl gravel, VIS: 40% shl (SP)	Nat w %	LL	PL	PI	Project	Ft. Pierce, FL, Shore Protection Project
										Area	Jacksonville District
										Boring No.	South Atlantic
											CB-STL-C10
										Date	01/09/1995

GRADATION CURVES



Sample No.	Elev / Depth	Classification	Nat w %	LL	PL	PI	Project
C10-2.3	-31.3 / 2.3	SAND, poorly graded, med to fine quartz, VIS: 10% shell (SP)					Ft. Pierce, FL, Shore Protection Project
							Jacksonville District
							South Atlantic
							Boring No. CB-STL-C10
							Date 01/09/1995

GRADATION CURVES



Sample No.	Elev / Depth	Classification	Nat w %	LL	PL	PI	Project
C10-7.6	-36.6 / 7.6	SAND, poorly graded, fine quartz VTS: 30% shell (SP)					Ft. Pierce, FL, Shore Protection Project
							Jacksonville District
							South Atlantic
							Boring No. CB-STL-C10
							Date 01/09/1995

