

DRILLING LOG		DIVISION SOUTH ATLANTIC		INSTALLATION JACKSONVILLE DISTRICT		Hole No. CB-MC99-11	
1. PROJECT MARTIN COUNTY		2. LOCATION (Coordinate or Station) X 774658 Y 1048502		10. SIZE AND TYPE OF BIT 4" dia. Vibracore		SHEET 1 OF 1 SHEETS	
3. DRILLING AGENCY WILMINGTON DISTRICT		4. HOLE NO. (As shown on drawing title and the number) CB-MC99-11		11. DATUM FOR ELEVATION SHOWN ON MSL MLLW		12. MANUFACTURER'S DESIGNATION OF DRILL VIBRA-CORE (SNELL)	
5. NAME OF DRILLER JERRY FULCHER CRANE OPERATOR		6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED DEC. FROM VERT.		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN DISTURBED 2 UNDISTURBED 0		14. TOTAL NUMBER CORE BOXES N/A	
7. THICKNESS OF OVERBURDEN N/A		8. DEPTH DRILLED INTO ROCK 0.0'		15. ELEVATION GROUND WATER N/A		16. DATE HOLE STARTED 08/25/99 COMPLETED 08/25/99	
9. TOTAL DEPTH OF HOLE 16.0'		17. ELEVATION TOP OF HOLE - 32.0 MLLW		18. TOTAL CORE RECOVERY FOR BORING N/A		19. SIGNATURE OF INSPECTOR Bob Keistler, PE	
ELEVATION MLLW	DEPTH feet	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE JARS	REMARKS (10-Hour 10-m. water base, depth of weathering, etc. if depth lost)	
-32.0	0		SAND - Poorly graded SILTY, FINE TO MEDIUM, GRAY, WITH SHELL FRAGMENTS (SP-SM)		1	Time Begin Vibracoring: 14:40 hrs. Soils field classified by Larry Benjamin, Civil Engineer Technician	
	2				0.5'		
	4				4.0'		
	6				2		
	6.7		6.7'		4.5'	VIBRACORE BORING From 0.0' to 16.0' Ran: 16.0' Rec: 6.7'	
-38.7	6.7		ASSUMED NOT RECOVERED				
	8						
	10						
	12						
	14						
-48.0	16		BOTTOM OF HOLE AT 16.0'				
			SOILS ARE FIELD VISUALLY CLASSIFIED IN ACCORDANCE WITH THE UNIFIED SOIL CLASSIFICATION SYSTEM				

PRELIMINARY