Hole No. PVC-46-84

| DRILLING LOG | DIVISION SOUTH ATLANTIC | INSTALLATION MOBILE DISTRICT | SHEET 1 OF 1 SHEETS |
|---|---|---|---|

| | |
|---|---|
| 1. PROJECT | BAY COUNTY, FLORIDA<br>PANAMA CITY BEACH - OFFSHORE |
| 2. LOCATION (Coordinates or Station) | ZONE FLN: N 421440 E 1590462 |
| 3. DRILLING AGENCY | MOBILE DISTRICT |
| 4. HOLE NO. (As shown on drawing title and file number) | PVC-46-84 |
| 5. NAME OF DRILLER | |
| 6. DIRECTION OF HOLE | [X] VERTICAL [ ] INCLINED DEG. FROM VERTICAL |
| 7. THICKNESS OF OVERBURDEN | - |
| 8. DEPTH DRILLED INTO ROCK | - |
| 9. TOTAL DEPTH OF HOLE | 19.0 (EL. -66.0) |
| 10. SIZE AND TYPE OF BIT | 4" X 30' VIBRACORE |
| 11. ELEVATION DATUM<br>COORDINATE DATUM | WATER LEVEL, FEET<br>STATE PLANE, NAD27, FEET |
| 12. MANUFACTORER'S DESIGNATION OF DRILL | JACKUP BARGE |
| 13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN | DISTURBED 3 / UNDISTURBED 0 |
| 14. TOTAL NUMBER CORE BOXES | 0 |
| 15. ELEVATION GROUNDWATER | 47.0' UNDERWATER |
| 16. DATE HOLE | STARTED 22 AUG 84 / COMPLETED 22 AUG 84 |
| 17. ELEVATION TOP OF HOLE | EL. -47.0 |
| 18. TOTAL CORE RECOVERY FOR BORING | |
| 19. SIGNATURE OF INSPECTOR | DRAFTED RLN / CHECKED |

| ELEVATION a | DEPTH b | LEGEND c | CLASSIFICATION OF MATERIALS (Description) d | % CORE RECOVERY OR W.C. e | BOX OR SAMPLE NO. f | REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g SPT BLOWS/FT |
|---|---|---|---|---|---|---|
| -53.2 | 5.0<br>6.2 | | (SP) SIY. W/TR. SHELL, GRAY AND BEIGE | | JAR #1 | LAB. CLASS. SP-SM, 5.7% FINES, MUNSELL 5Y 7/1 (L. GRAY) |
| -57.0 | 10.0 | | (CH) SANDY, GRAY | | JAR #2 | LAB. CLASS. CH, 51.8% FINES, MUNSELL 5Y 4/1 (D. GRAY) |
| -62.5 | 15.5 | | (SM) MED. GRAIN, WHITE AND BEIGE | | JAR #3 | LAB. CLASS. SP-SM, 6.6% FINES, MUNSELL 2.5Y 6/2 (L. BROWNISH GRAY) |
| -63.5 | 16.5 | | (CH) SANDY, BLACK | | | |
| -66.0 | 19.0 | | (SP) MED. GRAIN, WHITE | | | B.O.H. |