


DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30061


WORK ORDER NO. 9725
Req. No. 08-123-ENG-155-76
Req. No. FM-76-90



Sample No.	Elev or Depth	Classification	Nat w %	LL	PL	PI
1	Elev.	Tan poorly graded shelly	-	-	-	-
	-16.7 to	sand (SP). Shell is gravel				
	-17.7	size, coarse-medium sand size.				
	Depth					
	0.0-1.0	Shell approx. 43%				
GRADATION CURVES						
Project			JACKSONVILLE DISTRICT			
			Lab. No. 73/6679			
Area			Nassau County Beach Erosion			
Boring No.			CB-NC-5, Sample No. 1			
Date			18 March 1976			


DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30061

WORK ORDER NO. 9725
Req. No. 08-123-ENG-155-76
Req. No. FM-76-90



DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30061

WORK ORDER NO. 9725
Req. No. 08-123-ENG-155-76
Req. No. FM-76-90



DEPARTMENT OF THE ARMY, SOUTH ATLANTIC DIVISION LABORATORY
CORPS OF ENGINEERS, 611 SOUTH COBB DRIVE, MARIETTA, GA. 30061

WORK ORDER NO. 9725
Req. No. 08-123-ENG-155-76
Req. No. FM-76-90

