




DRILLING LOG		DIVISION SOUTH ATLANTIC		INSTALLATION MOBILE DISTRICT		Hole No. PVC-111-84 SHEET 1 OF 1 SHEETS	
1. PROJECT BAY COUNTY, FLORIDA PANAMA CITY BEACH - OFFSHORE				10. SIZE AND TYPE OF BIT 4" X 30' VIBRACORE			
2. LOCATION (Coordinates or Station) ZONE FLN: N 440721 E 1564543				11. ELEVATION DATUM WATER LEVEL, FEET COORDINATE DATUM STATE PLANE, NAD27, FEET			
3. DRILLING AGENCY MOBILE DISTRICT				12. MANUFACTURER'S DESIGNATION OF DRILL JACKUP BARGE			
4. HOLE NO. (As shown on drawing title and file number) PVC-111-84				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED 4 UNDISTURBED 0	
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES 0			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED    DEG. FROM VERTICAL				15. ELEVATION GROUNDWATER 51.0' UNDERWATER			
7. THICKNESS OF OVERBURDEN -				16. DATE HOLE STARTED 27 AUG 84    COMPLETED 27 AUG 84			
8. DEPTH DRILLED INTO ROCK -				17. ELEVATION TOP OF HOLE EL. -51.0			
9. TOTAL DEPTH OF HOLE 30.0 (EL. -81.0)				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR DRAFTED _____ CHECKED _____ RLN			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY OR W.C. e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g SPT BLOWS/FT	
	5.0		(CH) SP SC SM VARIOUS DPTHs. BLACK AND GREEN		JAR #1	LAB. CLASS. SP-SC, 5.9% FINES, MUNSELL 10YR 4/1 (D. GRAY)	
	10.0		(CH) SANDY W/TR. PEAT, BLACK		JAR #2	LAB. CLASS. SC, 22.3% FINES, MUNSELL 2.5Y N2/0 (BLACK)	
-64.0	13.0		(SM) , GREEN		JAR #3	LAB. CLASS. SP-SM, 6.2% FINES, MUNSELL 2.5Y N3/0 (V.D. GRAY)	
	15.0						
	20.0		(CH) SOME SILT, BLACK		JAR #4	LAB. CLASS. CH, 81.7% FINES, MUNSELL 2.5Y N2/0 (BLACK)	
	25.0						
-81.0	30.0					B.O.H.	