

DRILLING LOG		DIVISION <b>SOUTH ATLANTIC</b>		INSTALLATION <b>MOBILE DISTRICT</b>		Hole No. <b>V-56-94</b> SHEET <b>1</b> OF <b>2</b> SHEETS	
1. PROJECT <b>BAY CO FL OFFSHORE PANAMA CITY BEACHES NOURISHMENT</b>				10. SIZE AND TYPE OF BIT <b>3.5" x 25' VIBRACORE</b>			
2. LOCATION (Coordinates or Station) <b>ZONE FLN: N 413697 E 1603873</b>				11. ELEVATION DATUM <b>NGVD, FOOT U.S.</b> COORDINATE DATUM <b>STATE PLANE, NAD27, FOOT U.S.</b>			
3. DRILLING AGENCY <b>TET, INC.</b>				12. MANUFACTURER'S DESIGNATION OF DRILL <b>VIBRACORE</b>			
4. HOLE NO. (As shown on drawing title and file number) <b>V-56-94</b>				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED <b>5</b> UNDISTURBED <b>0</b>	
5. NAME OF DRILLER <b>CHARLIE WESTON</b>				14. TOTAL NUMBER CORE BOXES <b>0</b>			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED    DEG. FROM VERTICAL				15. ELEVATION GROUNDWATER			
7. THICKNESS OF OVERBURDEN <b>-</b>				16. DATE HOLE STARTED <b>27 NOV 94</b> COMPLETED <b>27 NOV 94</b>			
8. DEPTH DRILLED INTO ROCK <b>-</b>				17. ELEVATION TOP OF HOLE <b>EL. -38.4</b>			
9. TOTAL DEPTH OF HOLE <b>23.0 (EL. -61.4)</b>				18. TOTAL CORE RECOVERY FOR BORING <b>0</b>			
				19. SIGNATURE OF INSPECTOR <b>BRAD RALPH</b> DRAFTED <input type="checkbox"/> CHECKED <input type="checkbox"/> BCR    BCR			
ELEVATION <small>a</small>	DEPTH <small>b</small>	LEGEND <small>c</small>	CLASSIFICATION OF MATERIALS (Description) <small>d</small>	% CORE RECOVERY OR W.C. <small>e</small>	BOX OR SAMPLE NO. <small>f</small>	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) <small>g</small>	
-38.4	0.0	• • • • •	(SP) Gray fine SAND, trace shell	72% RECOV	S-1	LAB: (SP), 3% FINES (FINER THAN #200 SIEVE)	
	3.0	• • • • •					
	6.0	• • • • •	(SP) Brown fine SAND		S-2	LAB: (SP), 2% FINES	
-46.8	8.4	• • • • •					
	9.0	• • • • •	(SP-SM) Gray fine SAND		S-3	LAB: (SP-SM), 8% FINES	
-48.9	10.5	• • • • •					
	12.0	• • • • •	(SP) White fine SAND		S-4	LAB: (SP-SM), 8% FINES	
-52.1	13.7	• • • • •					
	15.0	• • • • •	(SP-SM) Gray fine SAND		S-5	LAB: (SP-SM), 8% FINES	
-54.9	16.5	• • • • •					
	18.0	X	SAMPLE NOT RECOVERED		X		
-59.4	21.0	X					

**ENG FORM 1836**  
(CADD Facsimile)

PROJECT **BAY CO FL OFFSHORE  
PANAMA CITY BEACHES NOURISHMENT**

HOLE NO. **V-56-94**

