

| DRILLING LOG | | Tetra Tech, Inc. | | INSTALLATION | | Hole No. CB-1 | |
|---|--|---|--|--|--|-----------------------------------|--|
| 1. PROJECT | | South Seas Plantation Beach Improvement | | 10. SIZE AND TYPE OF BIT | | 3" Sampler | |
| 2. LOCATION (Coordinates or Station) | | x = 421,347 ; y = 805,326 | | 11. DATUM FOR ELEVATION SHOWN (TUM or MSL) | | MSL | |
| 3. DRILLING AGENCY | | Ocean Seismic Survey, Inc. | | 12. MANUFACTURER'S DESIGNATION OF DRILL | | VIBRACORE | |
| 4. HOLE NO. (As shown on drawing title and file number) | | CB-1 | | 13. TOTAL NO. OF OVER- BURDEN SAMPLES TAKEN | | DISTURBED UNDISTURBED | |
| 5. NAME OF DRILLER | | Hume/Oblinger | | 14. TOTAL NUMBER CORE BOXES | | | |
| 6. DIRECTION OF HOLE | | <input type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT. | | 15. ELEVATION GROUND WATER | | Tidal | |
| 7. THICKNESS OF OVERBURDEN | | | | 16. DATE HOLE | | 27 Mar 79 | |
| 8. DEPTH DRILLED INTO ROCK | | | | 17. ELEVATION TOP OF HOLE | | -6' | |
| 9. TOTAL DEPTH OF HOLE | | | | 18. TOTAL CORE RECOVERY FOR BORING | | 1 | |
| | | | | 19. SIGNATURE OF INSPECTOR | | H. Miller (OSS); E. J. Olsen (Tt) | |

| ELEVATION | DEPTH | LEGEND | CLASSIFICATION OF MATERIALS (Description) | % CORE RECOV. ERY | SAMPLE NO. | REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) |
|-----------|-------|--------|--|-------------------------|---------------|--|
| -6.0 | 0.0 | | Shell, coarse, loose assorted, whole shells to fragments, various colors. | | | |
| -7.0 | 1.0 | | Shell, coarse to medium; little sand, medium to fine. | | | |
| -8.4 | 2.4 | | Shell, some sand, shell coarse to medium, medium compact; sand, medium to fine. | | 1 | |
| -8.0 | 3.0 | | Shell, coarse to medium; little sand medium to fine; light gray, medium compact. | | | |
| -10.8 | 4.8 | | Sand, trace shell fragments. Sand medium to fine, very compact. (SP) | | 2 | |
| -12.1 | 6.1 | | Sand and shell fragments. Sand medium to fine, very compact. (SP) | | | |
| -13.0 | 7.0 | | | | 3 | EXISTING |
| -15.6 | 9.6 | | Sand-fine to trace of medium size sand. Color-whitish gray, very compact. (SW) | | | |

Tt

PROJECT
South Seas Plantation
Beach Improvement

HOLE NO.
CB-1