



SIEVE ANALYSIS TOPB_VC_07.GPJ FL DEP ROSS.GDT 5/10/07



| Gravel | | Sand | | | Silt and Clay |
|--------|------|--------|--------|------|---------------|
| Coarse | Fine | Coarse | Medium | Fine | |

| Sample | Symbol | Elev. (ft) | USCS | % Fines | % Organics | % Carbonates | Median | Mean | Skew | Kurt | Sort | Sample Information | |
|---|--------|------------|------|----------------------------|------------|--|--------|------|-------|------|------|--------------------|--------------------------------|
| TPVC-07-09 #4 | —●— | -29.4 | SW | #200 - 1.36 #230 - 1.36 | | 40.00 | 2.58 | 2.08 | -1.67 | 5.28 | 1.3 | Project Name: | 2007 Sand Search Investigation |
| Comments: | | | | | | | | | | | | Analysis Date: | 01-19-07 |
| Depths and elevations based on measured values | | | | | | | | | | | | Analyzed By: | au |
|  | | | | | | Coastal Planning & Engineering 2481 NW Boca Raton Blvd, Boca Raton FL 33431 ph (561) 391-8102 fax (561) 391-9116 | | | | | | Easting (X, ft): | 972,441 |
| | | | | | | | | | | | | Northing (Y, ft): | 821,595 |
| | | | | | | | | | | | | Horizontal System: | NAD 1983 |
| | | | | | | | | | | | | Vertical System: | NAVD 88 |