

HOLE NO. CB - BP - 13

DRILLING LOG		South Atlantic		Jacksonville District		OF 1 SHEETS	
1. PROJECT Pinellas County B.E.C. Blind Pass				10. SIZE AND TYPE OF BIT see remarks			
2. LOCATION (Coordinates or Stationing) X-255,805 Y-1,237,673				11. DAY ON FOR ELEVATION SHOWN (YRM - MM)			
3. DRILLING AGENCY Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL Falling 1500			
4. HOLE NO. (As shown on drawing title and site number) CB-BP-13				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN DISTURBED UNDISTURBED			
5. NAME OF DRILLER J. Detloff				14. TOTAL NUMBER CORE BOXES 1			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED D.G. FROM VERT.				15. ELEVATION GROUND WATER Tidal			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE STARTED 22 May 78 COMPLETED 22 May 78			
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE -2.0			
9. TOTAL DEPTH OF HOLE 25.0'				18. TOTAL CORE RECOVERY FOR BORING 45			
				19. SIGNATURE OF INSPECTOR Geologist: J. Gentile			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of penetration, etc., if significant) g	
-2.0	0.0					BIT OR BARREL	
			SAND, fine to medium quartz, clean, tight, shelly, light gray. (SP)	55	1	2" SAMPLER	
						-7.0	
			Slightly silty from -12.0 to -19.0.	22	2	-12.0	
				26	3	" "	
						-17.0	
			Very tight, shelly, light gray, from -19.0 to -26.0.	42	4	" "	
						-22.0	
				80	5	" "	
-27.0	25.0					-27.0	