

DRILLING LOG		DIVISION <b>SOUTH ATLANTIC</b>		INSTALLATION <b>MOBILE DISTRICT</b>		Hole No. <b>V-51-94</b> SHEET <b>1</b> OF <b>1</b> SHEETS	
1. PROJECT <b>BAY CO FL OFFSHORE PANAMA CITY BEACHES NOURISHMENT</b>				10. SIZE AND TYPE OF BIT <b>3.5" x 25' VIBRACORE</b>			
2. LOCATION (Coordinates or Station) <b>ZONE FLN: N 420384 E 1596465</b>				11. ELEVATION DATUM <b>NGVD, FOOT U.S.</b> COORDINATE DATUM <b>STATE PLANE, NAD27, FOOT U.S.</b>			
3. DRILLING AGENCY <b>TET, INC.</b>				12. MANUFACTURER'S DESIGNATION OF DRILL <b>VIBRACORE</b>			
4. HOLE NO. (As shown on drawing title and file number) <b>V-51-94</b>				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED <b>4</b> UNDISTURBED <b>0</b>	
5. NAME OF DRILLER <b>CHARLIE WESTON</b>				14. TOTAL NUMBER CORE BOXES <b>0</b>			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED    DEG. FROM VERTICAL				15. ELEVATION GROUNDWATER			
7. THICKNESS OF OVERBURDEN <b>-</b>				16. DATE HOLE STARTED <b>27 NOV 94</b> COMPLETED <b>27 NOV 94</b>			
8. DEPTH DRILLED INTO ROCK <b>-</b>				17. ELEVATION TOP OF HOLE <b>EL. -43.1</b>			
9. TOTAL DEPTH OF HOLE <b>13.0 (EL. -56.1)</b>				18. TOTAL CORE RECOVERY FOR BORING <b>0</b>			
				19. SIGNATURE OF INSPECTOR <b>BRAD RALPH</b> DRAFTED <input type="checkbox"/> CHECKED <input type="checkbox"/> BCR    BCR			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY OR W.C. e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
-43.1	0.0	• • • • •	(SP) Gray medium to fine SAND	83% RECOV	S-1	LAB: (SP), 2% FINES (FINER THAN #200 SIEVE)	
	3.0	• • • • •					
-46.9	3.8	• • • • •					
		• • • • •					
		• • • • •	(SM) Gray silty medium to fine SAND, trace shell and organics		S-2	LAB: (SP-SM), 11% FINES	
-48.9	5.8	• • • • •	(SP-SM) Gray medium to fine SAND	83% RECOV	S-3	LAB: (SP-SM), 8% FINES	
-50.3	7.2	• • • • •					
		• • • • •	(SP) Gray medium to fine SAND	83% RECOV	S-4	LAB: (SP), 5% FINES	
	9.0	• • • • •					
-53.9	10.8	• • • • •	SAMPLE NOT RECOVERED	83% RECOV	S-5		
	12.0	• • • • •					
-56.1	13.0	• • • • •			S-6		
B.O.H.							