


| Gravel |      | Sand   |        |      | Silt and Clay |
|--------|------|--------|--------|------|---------------|
| Coarse | Fine | Coarse | Medium | Fine |               |

| Sample   | Symbol | Elev. (ft) | USCS | % Fines     | % Organics | % Carbonates | Median | Mean | Skew | Kurt | Sort | Sample Information |                                   |
|--|--------|------------|------|-------------|------------|--------------|--------|------|------|------|------|--------------------|-----------------------------------|
| 988526A  | —●—    | 7.4        | SP   | #230 - 0.03 |            | 67.20        | 1.34   | 1.34 | -0.5 | 6.81 | 0.47 | Project Name:      | Jupiter Island 10 - Beach Samples |
| Comments:  |        |            |      |             |            |              |        |      |      |      |      | Analysis Date:     | 01-26-11                          |
| Depths and elevations based on measured values   |        |            |      |             |            |              |        |      |      |      |      | Analyzed By:       | JR                                |
| <div style="display: flex; align-items: center;">  <div> <p>American Vibracore Services, Inc.</p> <p>1215 Wallace Drive</p> <p>Delray Beach, FL 33444</p> </div> </div> |        |            |      |             |            |              |        |      |      |      |      | Easting (X, ft):   | 946672.                           |
|  |        |            |      |             |            |              |        |      |      |      |      | Northing (Y, ft):  | 988683.                           |
|  |        |            |      |             |            |              |        |      |      |      |      | Horizontal System: | NAD 1983                          |
|  |        |            |      |             |            |              |        |      |      |      |      | Vertical System:   | NAVD 88                           |