


| Gravel | | Sand | | | Silt and Clay |
|--------|------|--------|--------|------|---------------|
| Coarse | Fine | Coarse | Medium | Fine | |

| Sample | Symbol | Elev. (ft) | USCS | % Fines | % Organics | % Carbonates | Median | Mean | Skew | Kurt | Sort | Sample Information | |
|---|--------|------------|------|-------------|------------|--------------|--------|------|------|------|------|--------------------|-----------------------------------|
| 970641A | —●— | 7.4 | SP | #230 - 0.40 | | | 1.18 | 1.04 | -1.6 | 7.81 | 0.82 | Project Name: | Jupiter Island 10 - Beach Samples |
| Comments: | | | | | | | | | | | | Analysis Date: | 01-14-11 |
| Depths and elevations based on measured values | | | | | | | | | | | | Analyzed By: | JR |
|  | | | | | | | | | | | | Easting (X, ft): | 952745. |
| | | | | | | | | | | | | Northing (Y, ft): | 970844. |
| | | | | | | | | | | | | Horizontal System: | NAD 1983 |
| | | | | | | | | | | | | Vertical System: | NAVD 88 |
| American Vibracore Services, Inc. 1215 Wallace Drive Delray Beach, FL 33444 | | | | | | | | | | | | | |