


Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
983302E	—●—	-8.6	SP	#230 - 0.91			1.11	1.06	-0.28	3.77	0.56	Project Name:	Jupiter Island 10 - Beach Samples
Comments:												Analysis Date:	01-14-11
Depths and elevations based on measured values												Analyzed By:	JR
<div style="display: flex; align-items: center; justify-content: space-between;"> <div style="text-align: center;">  <p>AMERICAN VIBRACORE SERVICES</p> </div> <div> <p>American Vibracore Services, Inc. 1215 Wallace Drive Delray Beach, FL 33444</p> </div> </div>												Easting (X, ft):	948869.
												Northing (Y, ft):	983532.
												Horizontal System:	NAD 1983
												Vertical System:	NAVD 88